



Technical Newsletter

PrismaPro using an “old” (1996) serial PCB

Problem: No communication when using E-prom V30 with “old” PCB

Cause: PCB is not exactly compatible with the later PCB.

Solution: Use E-prom V29 instead of E-prom V30, which can be used with PrismaPro.

How: Place E-prom V29 !!!**Check mach tune settings!!!**

The “old” PCB can be recognized by:

1. The big pushbuttons, _____
2. External diode in the transformer connection and the _____
3. Small PCB close to the E-prom. _____



Please distribute these Newsletters to your sales and service people

For more information please contact our Service Department at:

Telephone: 0031-(0)252 432 222

Fax: 0031-(0)252 432 282

E-mail: SERVICE@FLUIDMAN.NL